



Site Name	Feature Location	6 D's	Reasons	Existing species	Planting notes	Replant species
ROBERTSON ROAD	o/s 33	Dangerous	TR: Felling - Ganoderma infection. - Ganoderma sp. basal decay	Prunus serrulata	outside 33 in original location in tree pit.	Prunus (decorative cultivar)
ROBERTSON ROAD	o/s 48-50	Damaging	TR: Felling - Kerb disrupted by buttress rooting immediately behind	Prunus serrulata	Plant in new 800mm pit o/s 48-50 (same as felled tree)	Prunus (decorative cultivar)
ROBERTSON ROAD	o/s 52-54	Discriminatory	TR: Felling - F/W unusable/blocked	Prunus serrulata	Plant in new 800mm pit o/s 52-54 (same as felled tree)	Prunus (decorative cultivar)